Under Review Notification

Raised By: MYCHEL BEAUREGARD Product #: SWA6A, SWA10A, SWA15A, SWA25A, PWSA25A

Date: 19.07.29 **Product Name:** Swivel Hooks

		"Y" or "N" Required for Each Part Do not leave blank								
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	IPP Under Review (Enginer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
SWA6A-8	SWA6A REV. E	Y	Y	N	Y	Y	Y	Y	19-830	See below
SWA10A-8	SWA10A REV. 3	Υ	Υ	Ν	Υ	Υ	Υ	Υ	19-830	See below
SWA15A-8	SWA15A REV. 1	Υ	Υ	Ν	Υ	Υ	Υ	Υ	19-830	See below
SWA25A-8	SWA25A REV. 1	Υ	Υ	Ν	Υ	Υ	Υ	Υ	19-830	See below
PWSA25A-8	PWSA25A REV. A	Υ	Υ	Ν	Υ	Υ	Υ	Υ	19-830	See below

Description of Issue:

Electrical wire does not fit in hole and slot

No heat shrink call on the drawing

Electrical plugs are called in the BOM but are not required

Electrical wire need to be updated to have flexible wire type

Distribution:

VP Operations

Director of Operations Director Quality Assurance

QC Coordinator

Director of Engineering

Chief Engineer **Engineering Project Managers Engineering Clerk**

Customer Support Manager **Production Engineers Production Planners**

Purchasing Manager

Technical Support

Product Manager - Solutions Provider Supply Chain Director / Senior Buyer

Marketing Eugene